Cambium Networks	Document Number	FSB 9077
Cambium Networks, Inc. 3800 Golf Road Schaumburg, IL 60008, U.S.A.	Revision	000v001
FIELD SERVICE BULLETIN	Application	Global
R-Series Home Router MAC Address Issue	Effective Date	22 May 2019
	Expiry Date	N/A

## FIELD SERVICE BULLETIN

	BULLETIN TYPE	SEVERITY RECOMMENDATION	
X	Warranty Service	Χ	High – Perform immediately
X	Informational		Medium – Perform at next scheduled maintenance
	Customer Specific		Low – Perform when system exhibits symptoms

<u>SUBJECT:</u> Compatibility issue with TD90 Positioner (C000000L067A, C00000L068A, and C000000L069A) when used in combination with AC+DC Enhanced Power Injector 56V (C000065L002C)

# MODEL / SYSTEM AFFECTED: TD90 Positioner (C000000L067A, C000000L068A, and C000000L069A)

#### **REASON FOR Bulletin:**

There is a power compatibility issue with the TD90 when combined with the AC+DC Power Injector 56V. The power level provided by the power injector is higher than the circuitry in the TD90 board can except and will permanently damage the TD90 device and it will become inoperable.

The only power injectors approved for use with the TD90 are listed below. Use of any other power injector will void the product warranty.

CK-RPIDUG1A-WW - Rugged PIDU (Green), AC/DC

CK-RPIDUT1A-WW – Rugged PIDU (Tan), AC/DC

N000065L100C – AC Power Injector 56V

### NOTE:

#### **RESOLUTION:**

If you encounter this issue please open a support ticket with the Cambium Support team at the following URL:

https://support.cambiumnetworks.com

This Field Service Bulletin is issued by Cambium Networks in line with its policy of continual review and update of product quality, effectiveness and performance. Product performance or quality may be affected if the recommendations contained herein are not implemented, or not implemented as directed. This information is intended for personnel who have the proper tools, equipment and training to perform the tasks as described herein. Copyright © 2012 Cambium Networks, Inc.